

Murphy Benentay	Tap	Inside room 31 kitchenette in admin building	12/3/2019	HPA 2008	Lead	031	J	01	1
Murphy Benentay	Tap	Sirkin staff lounge	12/3/2019	HPA 2008	Lead	018	J	01	1
Murphy Benentay	Tap	Sirkin side preschool m39	12/3/2019	HPA 2008	Lead	026	J	01	1
Murphy Benentay	Fountain	Upper fountain near door 11	12/3/2019	HPA 2008	Lead	011	J	01	1
Murphy Benentay	Tap	Right side of three basins sirkin nearest door in kitchen	12/3/2019	HPA 2008	Lead	092	J	01	1
Murphy Benentay	Fountain	Fountain on right side of 6th floor side of room 11	12/3/2019	HPA 200		1	/E	rin kitchen	itchen

Muply Elementay	Fountain	Lower fountain on outside wall of 121	12/3/2019	HPA 2008	Lead	022	J	01	1

Analytical Notes And Definitions
J= Estimated Value (CI Flag)
MDL= Method Detection limit
ND= Not Detected above the method detection limit
PQL= Practical Quantitation limit